
Temora Sewage Treatment Plant EPA Licence Number 2523



Temora Shire Council Temora Sewage Treatment Plant Teal Street TEMORA NSW 2666

Location of Monitoring Point 5: Sewage Treatment Pond 6 - discharge to utilisation area

Monitoring Frequency required by licence: monthly

Date sample taken:12/07/2021Date sample sent to laboratory:12/07/2021Date data received from laboratory:28/07/2021Date data published:28/07/2021

Date published within 14 days: Yes

Summary of Results for: July 2021

| Pollutant | Unit of | Limit | Test | Limit |
|---------------------------|-----------|----------------------|--------|----------|
| | Measure | | Result | Exceeded |
| Biochemical Oxygen Demand | mg/L | 30 | 4 | No |
| Faecal Coliforms | per 100mL | 200 (80%) 600 (100%) | 10 | No |
| Oil & Grease | mg/L | 20 | 3 | No |
| рН | pH units | 5.5 - 9.5 | 7.6 | No |
| Total Suspended Solids | mg/L | 40 | 16 | No |
| Ammonia | mg/L | - | 4.4 | No |
| Conductivity | μS/cm | - | 687 | No |
| Nitrate | mg/L | - | 1.9 | No |
| Total Nitrogen | mg/L | - | 18 | No |
| Total Phosphorous | mg/L | - | 3.72 | No |