
Temora Sewage Treatment Plant EPA Licence Number 2523



Temora Shire Council Temora Sewage Treatment Plant Teal Street TEMORA NSW 2666

Location of Monitoring Point 5: Sewage Treatment Pond 6 - discharge to utilisation area

Monitoring Frequency required by licence: monthly

Date sample taken:29/03/2022Date sample sent to laboratory:29/03/2022Date data received from laboratory:2/05/2022Date data published:4/05/2022

Date published within 14 days: Yes

Summary of Results for: March 2022

Pollutant	Unit of	Limit	Test	Limit
	Measure		Result	Exceeded
Biochemical Oxygen Demand	mg/L	30	2	No
Faecal Coliforms	per 100mL	200 (80%) 600 (100%)	4500	Yes
Oil & Grease	mg/L	20	1	No
рН	pH units	5.5 - 9.5	8.3	No
Total Suspended Solids	mg/L	40	19	No
Ammonia as N	mg/L	-	0.6	No
Conductivity	μS/cm	-	891	No
Nitrate/Nitrate as N	mg/L	-	1.7	No
Nitrogen, total	mg/L	-	5	No
Total Kjeldahl Nitrogen	mg/L	-	3	No
Phosphorous, total	mg/L	-	3.89	No